

Fuel Turbopumps

CIL Item:

B200-26

Component:

High Pressure Fuel Turbopump RS007501

Part Number:

Failure Mode:

Structural failure.

Prepared:

D. Early T. Nguyen 4/21/99

Approved: Approval Date: Change #:

Directive #:

CCBD ME3-81-5206

Page:

| Phase | Fallure / Effect Description | Criticality Hazard Reference |
|--------------|--|---------------------------------|
| PSMCD 4,1 | Immediate loss of turbopump gulput. External damage to engine from hydrogen fire or explosion and aft compartment overpressurization. Loss of vehicle. | 1 ME-D1S M, |
| | Redundancy Screens: SINGLE POINT FAILURE: N/A | ME-D1A,C ME-D3P,D |

SSME FMEA/CIL DESIGN

Component Group:

Fuel Turbopumps

CIL Item:

B200-26

Component:

High Pressure Fuel Turbopump

Part Number: Failure Mode: RS007601 Structural lailure. Prepared: Approved: D. Early T. Nguyan

Approval Date: Change #:

: 4/21/99

Okective #:

CCBD ME3-01-5206

Page:

1 of 2

Design / Document Reference

FAILURE CAUSE: A: Fallure of parent metal or welds in main housing, intet housing, thrust bearing housing or thrust bearing cap.

THE TURBOPUMP MAIN HOUSING (1) IS COMPRISED OF 3 PRIMARY SECTIONS, THE PUMP SECTION. THE TURBINE SECTION, AND THE PUMP DISCHARGE VOLUTE SECTION. THE TURBOPLIMP MAIN HOUSING IS A WELDMENT OF MACHINED INCONEL 718 FORGINGS (2) EXCEPT FOR THE VOLUTE BACK PLATE, WHICH IS AN INCONEL 718 INVESTMENT CASTING (2) INCONEL 718 WAS SELECTED FOR ITS STRENGTH, RESISTANCE TO CORROSION AND STRESS CORROSION CRACKING, AND CRYOGENIC DUCTILITY. THE MATERIAL IS SOLUTION TREATED AGE-HARDENED, AND ANNEALED TO IMPROVE MECHANICAL PROPERTIES. INCONEL 718 HOUSING SURFACES AND WELDS EXPOSED TO HIGH-PRESSURE HYDROGEN GAS USE COPPER PLATING AND INCOLOGY 88 WELD OVERLAY, RESPECTIVELY, TO PROVIDE HYDROGEN ENVIRONMENT PROTECTION. THE PUMP SECTION IS A THIN SHELL OUTER BARREL STRUCTURE THAT HAS NO HIGH-PRESSURE SEALS. A SEPARATE INTERNAL DIFFUSER CROSS OVER ASSEMBLY CARRIES THE HIGH PRESSURE LOADS LEAKAGE INTO THE MAIN HOUSING IS VENTED TO THE PUMP INLET. THE THIRD-STAGE DIFFUSER VANES ARE MACHINED INTO THE PUMP SECTION AT THE ENTRY OF THE DISCHARGE VOLUTE. THE PUMP DISCHARGE VOLUTE SECTION IS THE STRUCTURAL MEMBER THAT CARRIES THE HIGH-PRESSURE PUMP DISCHARGE PRESSURE LOAD. THE VOLUTE LINER SHEET METAL IS MANUFACTURED UTILIZING INCONEU718 AND PROVIDES THE FLOW PASSAGES THAT ARE HYDRODYNAMICALLY SHAPED FOR CONSTANT ANGULAR MOMENTUM TO MINIMIZE DIFFUSION LOSSES. THE VOLUTE BACK PLATE PROVIDES THE STATIONARY MEMBER OF THE BALANCE PISTON. THE TURBINE SECTION CONSISTS OF THE TURBINE OUTER RING AND THE INNER RING. THE INNER RING IS INTEGRAL TO THE OUTER RING THROUGH 12 STRUTS. THERMALLY INDUCED LCF CRACKING OF THE OUTER RING (G-6) HAS OCCURRED. G-6 FLANGE CRACKS ARE MAPPED AND EVALUATED AT EACH TURBOPUMP OVERHAUL (3). THE CRACKING LENGTH IS CONTROLLED TO PRECLUDE THE CRACK FROM REACHING THE STATIC SEAL GROOVE AND REDUCING THE EFFECTIVENESS OF THE SEAL. CONTINUED USE WITH ALLOWABLE DISCREPANCIES RESULTING FROM OPERATION IS EVALUATED AND CONTROLLED PER THE REQUIREMENTS OF THE MAINTENANCE CONTROL DOCUMENT (4). THE TURBINE EXHAUST TURNAROUND DUCT. COOLANT LINER, AND STRUT CANS ARE MANUFACTURED DTILIZING HAYNES 188 SHEET METAL (2). HAYNES 188 WAS SELECTED FOR ITS STRENGTH AT ELEVATED TEMPERATURES AND ITS LOW-CYCLE FATIGUE LIFE PROPERTIES IN HIGH-PRESSURE HYDROGEN. THE TURBINE EXHAUST TURNAROUND DUCT HAS 12 STIFFNER VANES AT THE DISCHARGE OF THE SECOND-STAGE BLADES AND 12 POSTS LOCATED BETWEEN THE TURBINE DISCHARGE STRUTS, TO ADD RIGIDITY TO THE TURNAROUND DUCT SHEET METAL. TURBINE-END HOUSING COOLANT IS PROVIDED BY HYDROGEN FLOWING FROM THE BALANCE PISTON CAVITY BETWEEN THE COOLANT LINER AND THE TURBINE OUTER RING. INTO THE STRUTS, AND THEN THROUGH THE INNER RING. THE LIFT-OFF SEAL ORAIN LINE AND BALANCE CAVITY PRESSURE LINE ARE FABRICATED UTILIZING 321 CRES TUBING (2). THIS MATERIAL WAS SELECTED FOR ITS CRYOGENIC MECHANICAL PROPERTIES, DUCTILITY, AND ITS INSENSITIVITY TO HYDROGEN ENVIRONMENT EMBRITTLEMENT. THE HOUSING IS PROOF PRESSURE TESTED TO VERIFY ITS STRUCTURED INTEGRITY (5).

THE PUMP INLET (E) IS A WELDMENT OF FORGED AND SHEET SAL-2.55% (ELI) TITANIUM ALLOY. THE PUMP INLET RECEIVES LIQUID HYGROGEN FROM THE LIPETP DISCHARGE DUCT AND GUIDES THE FLOW INTO THE INLET OF THE FIRST-STAGE IMPELLER. BRESO HOLES IN THE INLET DOME PROVIDE OVERPRESSURE PROTECTION FOR THE INLET AND HOUSING (?) RESULTING FROM LEAKAGE PAST THE HOUSING AND DIFFUSER PISTON RING SEALS. THE INLET IS PILOTED ON AND BOLTED TO THE MAIN HOUSING. THE INLET IS PROOF PRESSURE TESTED TO VERIFY ITS STRUCTURAL INTEGRITY. THE THRUST BEARING HOUSING (?) PILOTS ON AND IS BOLTED (8) TO THE PUMP INLET. THE THRUST BEARING CAP (19) IS BOLTED (10) TO AND PILOTED BY THE THRUST BEARING HOUSING AND PROVIDES ACCESS FOR THRUST BEARING INSPECTION WITHOUT REMOVAL OF THE THRUST BEARING HOUSING. THE PUMP INLET AND THRUST BEARING CAP ARE MANUFACTURED UTILIZING SAL-2.55% (ELI) TITANIUM ALLOY (2). THIS ALLOY WAS SELECTED FOR ITS LOW DENSITY STRENGTH, TOUGHNESS. FATIGUE PROPERTIES AT CRYOGENIC TEMPERATURES, RESISTANCE TO CORROSION AND STRESS CORROSION CRACKING AND RESISTANCE TO HYDROGEN ENVIRONMENT EMBRITTLEMENT AT OPERATING TEMPERATURES (2). THE INLET AND CAP ARE ANNEALED. THE INLET IS STRESS RETIEVED AFTER WELDING. THRUST BEARING HOUSING IS MANUFACTURED UTILIZING A HASTLELLOY B FORGING (2). HASTELLOY B WAS SELECTED FOR ITS STRENGTH, RESISTANCE TO CORROSION AND STRESS CORPOSION CRACKING, LOW THERMAL EXPANSION, AND INSENSITIVITY TO HYDROGEN ENVIRONMENT EMBRITTLEMENT AT OPERATING TEMPERATURES (2). THE MATERIAL IS ANNEALED TO IMPROVE MATERIAL PROPERTIES. THE MAIN HOUSING AND PUMP INLET HAVE BEEN DESIGN VERIFICATION TESTED FOR LOW CYCLE FAI IGUE. PRIMARY STRESS SAFETY FACTORS, AND DEFLECTIONS (11).

^(*) RSC07577 , RS007568; (2) RSS-8580-10 (3) RL00528; (4) RSS-8792; (5) RL00024 (6) RSC07535, RS007512 (7) R8019204; (6) ND112-0001; (9) RS007540; (10) MS9575 (11) RSS-404-26, RSS-404-40

Fuel Turbopomps

CIL Itam: B200-25

Companent:

High Pressure Fuel Turbopump

Part Number: Failure Mode:

RS007501 Structural fallure. Prepared: Approved: Approval Date: O. Early T. Nguyen 4/21/99

Change #; Directive #;

CGBD ME3-01-5206

Page:

2 of 2

Design / Document Reference

FAILURE CAUSE: B: Diffuser cracking causing overpressurization of pump housing.

THE FLOW FROM THE FIRST-AND SECOND-STAGE (MPELLERS PASSES THROUGH TWO DIFFUSER (1) (2) STAGES, WHICH GUIDES THE FLUID FROM THE DISCHARGE OF ONE IMPELLER TO THE INLET OF THE NEXT. THE DIFFUSERS ARE MANUFACTURED UTILIZING ALUMINUM ALLOY TENS-50-TGC CASTINGS (3). THIS MATERIAL WAS SELECTED FOR ITS STRENGTH TO WEIGHT RATIO, RESISTANCE TO CORROSION AND STRESS CORROSION CRACKING. ITS STRENGTH IS NOT DEGRADED IN HYDROGEN ENVIRONMENT. THE MATERIAL IS SOLUTION TREATED, AGE. HARDENED, AND ANODIZED. THE DIFFUSERS SUPPORT THE FRONT (4) AND REAR LABYRINTH (5) SEALS AND THE INTERSTAGE SEALS (6). PISTON RINGS (7) ARE USED TO SEAL AT THE DIFFUSER PILOT DIAMETERS. LEAKAGE FLOW PAST THESE SEALS IS VENTED TO INLET PRESSURE TO REDUCE THE LOADS ON THE HOUSING CASING (8). THE FIRST-STAGE DIFFUSER PINNED TO THE SECOND-STAGE DIFFUSER, WHICH IN TURN IS INDEXED TO THE HOUSING. IRREGULARLY SPACED LUGS IN THE DIFFUSER AND PROVIDE FREEDOM FOR THE DIFFUSERS TO MOVE AXIALLY RELATIVE TO THE HOUSING, WHILE REACTING TO THE TORQUE LOADS. THE DIFFUSERS ARE POSITIONED AXIALLY RELATIVE TO THE INLET IMPELLERS AND EACH OTHER BY USE OF SHIMS (9). THE SECOND-STAGE IS RADIALLY PILOTED BY A LIP ON THE HOUSING. THE FIRST-STAGE DIFFUSER IS RADIALLY PILOTED BY A LIP ON THE INLET. A PRELOAD SPRING (10) BETWEEN THE SECOND-STAGE DIFFUSER AND THE HOUSING KEEPS THE DIFFUSER AND SHIM STACK TIGHT FOR HANDLING AND SHIPPING PURPOSES. IN OPERATION THE PRESSURE FORCES LOAD THE STACK AGAINST THE INLET. THE DIFFUSER IS PROOF PRESSURE TESTED TO VERIFY ITS STRUCTURAL INTEGRITY (11). DESIGN VERIFICATION TESTING DEMONSTRATED THE FACTOR OF SAFETY FOR BURST ON A SECOND-STAGE DIFFUSER HAVE BEEN DESIGN VERIFICATION TESTED FOR STRESS SAFETY FACTOR, LOW CYCLE FATIGUE LIFE, AND DEFLECTIONS (12).

(1) RS007527; (2) RS007532; (3) RSS-8580-10; (4) R0012199 R0012205; (5) RS007529; (6) RS007531; (7) RES1261, RES1167; (8) RS007577, RS007568; (9) RS007564; (10) RS007507; (11) RL00023 (12) RSS-404-22

FAILURE CAUSE: ALL CAUSES

THE HIGH AND LOW CYCLE FATIGUE LIFE FOR PUMP INLET. THRUST BEARING HOUSING, THRUST BEARING CAP, THE FIRST-STAGE DIFFUSER AND THE SECOND-STAGE DIFFUSER MEET CEI REQUIREMENTS (1). THE MAIN HOUSING IS LOW AND HIGH CYCLE FATIGUE LIFE LIMITED BY MAJOR WAIVER (6). THE MINIMUM FACTORS OF SAFETY FOR THESE PARTS MEET CEI REQUIREMENTS (2). THE HARDWARE PARENT MATERIALS WERE CLEARED FOR FRACTURE MECHANICS/INDE FLAW GROWTH SINCE THEY ARE NOT FRACTURE CRITICAL PARTS. EXCEPT FOR THE HOUSING ASSEMBLY WHICH WAS CLEARED BY CRITICAL INITIAL FLAW SIZE DETECTABILITY AND THE INLET ASSEMBLY WHICH WAS CLEARED BY RISK AND IDENTIFIES THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE AND THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE AND THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE AND THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE FOR FLIGHT BY RISK ASSESSMENT (4) REUSE OF PARTS DURING OVERHAUL IS CONTROLLED BY THE REQUIREMENTS OF THE OVERHAUL SPECIFICATION (5)

(1) Rt 00532, CP320R0003B; (2) RSS-8546-16, CP320R0003B; (3) NASA TASK 117; (4) RSS-8756; (5) RL0052B, (6) DAR 1199 DAR 2513 DAR 2091

SSME FMEA/CIL INSPECTION AND TEST

Component Group:

Fuel Turbopumps

CIL Item: Component:

B200-26

Parl Number:

High Pressure Fire! Turbopump RS007501

Failure Mode:

Structural failure.

Prepared:

Approved:
Approval Date:
Change #:
Directive #;

D. Early 7. Nguyen 4/21/99

CCBD ME3-01-5206

| Failure Causes | Significant Characteristics | formation 1 T-45 | 1 of 3 | |
|----------------|-----------------------------|---|---|--|
| 4 | INLET ASSEMBLY | Inspection(s) / Test(s) | Dodument Reference | |
| • | INLET ASSEMBLY | | RS007535 RS007512 | |
| | MATERIAL INTEGRITY | MATERIAL INTEGRITY IS VERIFIED PER DRAWING AND SPECIFICATION REQUIREMENTS. | R\$007535 R\$007512 RB0170-152 | |
| | | FORGING IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS. | RA0115-116 | |
| | | THE INLET IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS. | RAD115-116 RL00314 | |
| | WELD INTEGRITY | ALL WELDS ARE INSPECTED TO ORAWING AND SPECIFICATION REQUIREMENTS PER WELD CLASS INSPECTIONS INCLUDE: VISUAL, DIMENSIONAL, PENETRANT, RADIOGRAPHIC, DLTRASONIC, AND FILLER MATERIAL, AS APPLICABLE. | RL10011 RA0507-094 RA0115-116 RA0115-006 RA1115-001 RA0115-127 | |
| | HEAT TREAT | HEAT TREAT IS VERIFIED PER SPECIFICATION REQUIREMENTS AFTER WELDING. | RA0111-024 | |
| | ASSEMBLY INTEGRITY | THE INLET PROOF PRESSURE TEST IS PERFORMED PER SPECIFICATION REQUIREMENTS. | RL00024 | |
| | HOUSING | | RS007568 | |
| | MATERIAL INTEGRITY | MATERIAL INTEGRITY IS VERIFIED PER DRAWING AND SPECIFICATION REQUIREMENTS | RS007568 RB0170-153 RB0170-154 | |
| | | FORGING IS PENETRANT AND ULTRASONIC INSPECTED PER SPECIFICATION REQUIREMENTS. | RA0115-116 RA0115-012 | |
| | | HOUSING IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS | RA0115-116 | |
| | WELD INTEGRITY | ALL WELDS ARE INSPECTED PER DRAWING AND SPECIFICATION REQUIREMENTS PER WELD CLASS. INSPECTIONS INCLUDE: VISUAL, DIMENSIONAL, PENETRANT, RADIOGRAPHIC, ULTRASONIC, AND FILLER MATERIAL, AS APPLICABLE. | RL10011 RA0607-094 RA0115-116 RA0115-006 RA1115-001 RA0115-127 | |
| | HEAT TREAT | HEAT TREAT IS VERIFIED PER SPECIFICATION REQUIREMENTS. | RA0611-020 | |
| | SURFACE FINISH | COPPER PLATING AND PLASMA SPRAYING IS VERIFIED PER SPECIFICATION REQUIREMENTS. | RA1109-002 RA0109-018 RA0109-019 | |
| | ASSEMBLY INTEGRITY | THE HOUSING PROOF PRESSURE TEST IS PERFORMED PER SPECIFICATION REQUIREMENTS. | RL00143 | |
| | HOUSING, BEARING THRUST | | R0019204 | |
| | MATERIAL INTEGRITY | MATERIAL INTEGRITY IS VERIFIED PER DRAWING REQUIREMENTS. | R0019204 | |

B - 178

CIL Itam: Companent: Part Number: Fire! Turbopumps

B200-26 High Pressure Fuel Turbopump RS007501

Failure Mode: Structural failure.

Prepared: Approved: Approval Date: Change #: D. Early T. Nguyen 4/21/99

Directive #:

GCBD ME3-01-5206

Page

| 6.1. 0 | : | Page; | 2 of 3 | | | | | |
|----------------|--|--|--------------------------|--|--|--|--|--|
| Feiture Causes | Significant Characteristics | 100000000000000000000000000000000000000 | | | | | | |
| A | MATERIAL INTEGRITY | FORGING IS PENETRANT AND ULTRASONIC INSPECTED PER SPECIFICATION REQUIREMENTS. | RA0115-116 RA0115-012 | | | | | |
| | | THE HOUSING IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS. | RA0115-116 | | | | | |
| | COVER | | RS007540 | | | | | |
| | MATERIAL INTEGRITY | MATERIAL INTEGRITY VERIFIED PER SPECIFICATION REQUIREMENTS | RB0170-079 | | | | | |
| | | FORGING IS PENETRANT AND ULTRASONIC INSPECTED PER SPECIFICATION REQUIREMENTS. | RA0115-116 RA0115-012 | | | | | |
| | | COVER IS PENETRANT INSPECTED PER SPECIFICATION REQUIREMENTS. | RA0115-116 | | | | | |
| 0 | DIFFUSER, ASSEMBLY FIRST INTERSTAGE | | RS007527 | | | | | |
| | MATERIAL INTEGRITY | MATERIAL INTEGRITY IS VERIFIED PER SPECIFICATION REQUIREMENTS. | RB0170-099 | | | | | |
| | | CASTING IS RADIOGRAPHIC INSPECTED PER SPECIFICATION REQUIREMENTS. | RL10003 | | | | | |
| | | PROOF PRESSURE TEST IS PERFORMED PER SPECIFICATION REQUIREMENTS. | RLG0023 | | | | | |
| | | SURFACE IS PENETRANT INSPECTED AFTER PROOF PRESSURE TEST PER SPECIFICATION REQUIREMENTS. | RA0115-116 | | | | | |
| | HEAT TREAT | HEAT TREAT IS VERIFIED PER DRAWING REQUIREMENTS. | RS007532 | | | | | |
| | SURFACE FINISH | ANODIZED FINISH IS VERIFIED PER DRAWING AND SPECIFICATION REQUIREMENTS. | RA1609-003 RS007527 | | | | | |
| | OIFFUSER ASSEMBLY | | RS007532 | | | | | |
| | MATERIAL INTEGRITY | MATERIAL INTEGRITY IS VERIFIED PER SPECIFICATION REQUIREMENTS. | RB0170-099 | | | | | |
| | | PROOF PRESSURE TEST IS PERFORMED PER SPECIFICATION REQUIREMENTS. | RL00023 | | | | | |
| | | DIFFUSER ACCESSIBLE SURFACES ARE PENETRANT INSPECTED PRIOR TO AND FOLLOWING PROOF PRESSURE TEST PER SPECIFICATION REQUIREMENTS. | RAD115-116 | | | | | |
| | | DIFFUSER HIDGEN SURFACES ARE PENETRANT INSPECTED PRIOR TO AND FOLLOWING PROOF PRESSURE TEST PER SPECIFICATION REQUIREMENTS | RA0115-116 RL00343 | | | | | |
| | HEAT TREAT | HEAT TREAT IS INSPECTED PER DRAWING REQUIREMENTS | RS007532 | | | | | |
| | SURFACE FINISH | THE ANODIZED FINISH IS VERIFIED PER DRAWING AND SPECIFICATION REQUIREMENTS | RA1609-003 RS007532 | | | | | |
| ALL CAUSES | KPFTP | - | RS007501 | | | | | |
| | CLEANLINESS OF COMPONENTS | COMPONENTS ARE VERIFIED OF PANED PER SPECIFICATION REQUIREMENTS | RL†0001 | | | | | |
| | ASSEMBLY INTEGRITY | THE PUMP SUBASSEMBLIES ARE INSPECTED DURING OVERHAUL PER SPECIFICATION REQUIREMENTS. INSPECTIONS INCLUDE: VISUAL, DIMENSIONAL, PENETRANT, AND REPLACEMENT OF USAGE ITEMS AS APPLICABLE, PER OVERHAUL CLASSIFICATION. | RL00528 RA0115-116 | | | | | |

Fool Turbopumps

Structural fallure.

CiL flem: Component: B200-26

Part Number: Fallure Mode: High Pressure Fuel Turbopump RS007504

Prepared:

Approved: Approval Date:

D. Early T. Nguyen 4/21/89

Change #: Directive #:

CCBD ME3-01-5208

Рвае:

3 of 3

| -· ·- | | | 3 U) 3 |
|-------------------|--|--|---|
| Failure Causes | Significant Characteristics | Inspection(s) / Test(s) | Document Reference |
| ALL CAUSES | ASSEMBLY INTEGRITY | OPERATION/PERFORMANCE IS VERIFIED BY ENGINE HOT FIRE TESTING AND 2ND E&M TESTS ON INSPECTIONS. | RL00050-04 RL00056-06 RL00056-07 RL00461 |
| | | TORQUE CHECKS ARE PERFORMED PRIOR TO EACH FLIGHT | OMRSD V418S0.070 |
| | SHAFT TRAVEL IS PERFORMED PRIOR TO EACH FLIGHT. A HELIUM SIGNATURE LEAK TEST IS PERFORMED PRIOR TO EACH FLIGHT | SHAFT TRAVEL IS PERFORMED PRIOR TO EACH FLIGHT. | |
| | | OMRSD \$00000,950 | |
| | | DATA FROM PREVIOUS FLIGHT OR HOT FIRE IS REVIEWED FOR PROPER TURROPUMP OPERATION/PERFORMANCE. (LAST TEST) | MSFC PLN 1228 |
| | | | |

Failure History:

Comprehensive failure history data is maintained in the Problem Reporting database (PRAMS/PRACA)

Reference. NASA letter \$A21/88/308 and Rockeldyne letter 88RC09761.

Operational Use:

Not Applicable.

B - 180

B - 181

SSME FMEAICIL FIELD CONFIGURATION VARIANCES FROM CIL RATIONALE

Component Group:

Fuel Turbopumps

Item Name:

High Pressure Fuel Turbonump

Hem Number: Part Number: B200 RS007501 Prepared: Approved: D. Early T. Nguyen 4/21/99

Approval Date: Change #: Directive #:

CCBD MET-01-ETOR

| | | Directive #; | CCBD ME3-01-5208 |
|---|---|---|---|
| Base Line Rationale | Veriance | Page: | 1 of 2 |
| 1. H200-15 RS007502; CAUSE A. | | Change Rationale | Variani Dash Numbe |
| B200-24; RS007605; CAUSE A THE INNER AND OUTER BEARING RACES ARE EDDY CURRENT INSPECTED PER RL00743. | BEARING RACES RECEIVED FROM SUPPLIER SPLIT BALL BEARING INCORPORATED RECEIVED NO GENERAL EDDY CURRENT INSPECTION | GENERAL EDDY CURRENT INSPECTION OF RACES REPLACES TYPE IVC IN PENETRANT INSPECTION IN DETECTING SURFACE FLAWS USE AS IS RATIONALE: 1. RACES SUPPLIED BY SPLIT BALL BEARING INCORPORATED RECEIVED 10X VISUAL AND TYPE IVC PENETRANT INSPECTION INSTEAD OF GENERAL EDDY CURRENT INSPECTION. FLAW OFFECTABILITY RELIABILITY LEVELS RETWEEN PENETRANT AND GENERAL EDDY CURRENT INSPECTIONS ARE 0.060 AND 0.057 RESPECTIVELY. | SEE DAR 2745 FOR VARIANT PART SERIAL NUMBERS. |
| 2. B200-13 R5007527, RS007532, CAUSE A & B. B200-26; RS007532; CAUSE B. DIFFUSER HIDDEN SURFACES ARE PENETRANT INSPECTED PER RL00343, | SGME DIFFUSERS MAY NOT RECEIVE THE POST PROOF TEST HIDDEN SURFACE III PENETRANT INSPECTION | USE AS IS RATIONALE 1 IMPLEMENTATION OF HIDDEN SURFACE INSPECTION REQUIREMENT IS NOT A RESULT OF AN OBSERVED HARDWARE ANAQMALY BUT AS A RESULT OF ROCKETDYNE'S STAND DOWN. | SEE DAR 2751 FOR VARIANT PART SERIAL NUMBERS |
| B200-14 CAUSE A, RS007568 B200-21 CAUSE B, RS007568 B200-26 CAUSE A, RS007568 WELD JOINTS RS007568 TABLE B200 HPF IP FMEA/CIL WELD BOINTS RS037568 HOUSING CURRENT CONFIGURATION IS BITE ONE(1) PIECE "-1121 CAP, JSING FOUR (4) WELDS AND FOUR (4) WELDS AND | SOME HOUSINGS (POSSIBLY TWO) MAY HAVE BEEN FABRICATED WITH THE TWO (2) PIECE *-113" CAPS (THIS HAS AN EXTRA WELD: #13 AND THREE FXTRA WELD NUMBERS 13, 58 69) | TO REDUCE CONFUSION ON THE DRAWING AND ON THE MANUFACTURING FLOOR | SEE MCR 2524. SAME -113 DASH NUMBER. |
| + B200-02; CAUSE A, R\$097524 CAUSE B, R\$007524; CAUSE C, R\$007524 | SOME TURBINE BEARING SUPPORTS (RS007524) ARE FABRICATED USING A WSLDMENT OF HAYES 188 SHEET METAL INSTEAD OF THE EDM FORGING. | TIIGH CYCLE FATIGUE INDUCED INLET SHEET METAL CRACKS OO OCCUR FROM THE CPERATIONAL ENVIRONMENT EXPERIENCED DURING ENGINE OPERATION. THE CRACKING IS CONTROLLED PER THE REQUIREMENTS:OF THE SHEET METAL INSPECTION SPECIFICATION (RL00655) WHICH LIMITS THE CRACKING LENGTH, SPACING, AND SHAPE, TO PRECLUDE SHEET METAL, PIECES FROM DISLODGING. THE CRITERIA IS BASED ON CRACK GROWTH RATES AND ENGINE TEST EXPERIENCE. ANY CRACKS, WHICH EXCEED THE SPECIFICATION LIMITS, ARE WELD REPAIRED IRF0001-007). THE TURBINE BEARING SUPPORT WITH WELDED SHEET METAL IS LIFE LIMITED BY MAJOR WAIVER DAR 2709. | RS007524-201 AND SUBS. |

Component Group: Item Name:

Fuel Turbopumps High Pressure Fuel Turbopump B200

Item Number: Part Number:

RS007501

Prepared: Approved: Approvel Date: Change #: Oirective #:

D. Early T. Nguyen 4/21/99 2 CCBD ME3-01-5206

Pager

| | | Page: | 2 of 2 |
|---|--|---|---------------------------|
| Base Line Rationale | Variance | Change Rationale | Variant Dash Number |
| 5 B200-16 CAUSE A, B200-17 CAUSE A, B200-18 CAUSE A, B200-19 CAUSE A, B200-22; CAUSE A,B,C,E | SOME LIFT-OFF SEAL HOUSING DRAIN LINES ARE FABRICATED USING INTERSECTING LINE DRILLED HOLES. THE HOLE THAT INTERSECTS THE OUTSIDE DIAMETER OF THE HOUSING FLANGE HAS A PLUG INSTALLED. THE PLUG IS THEN WELDED AT THE HOUSING OUTSIDE DIAMETER TO FORM A TIGHT GAS SEAL. | LOW CYCLE FATIGUE CRACKING HAS BEEN OBSERVED IN THE PLUG WELD, CRACK INITIATION AND PROPAGATION OCCURS AT SHUTDOWN/COOLDOWN ALL UNITS RECEIVE A STANDARD POST FLIGHT INSPECTIONS BY LEAK CHECK. LEAK CHECK POST FLIGHT WILL DETECT A CRACK PRIOR TO REFUGHT. POST LEAKAGE AT THE DRAIN LINE IS LIMITED TO 10 SCIM. ALL FLIGHT UNITS WILL CONTINUE TO RECEIVE A LEAK CHECK POST FLIGHT FOR THE DRAIN LINE PLUG WELD UNTIL THE ENTIRE FLEET IS RETROFIT WITH THE EDM DRAIN LINE CONFIGURATION | R0019230-071 AND SUBS. |

SSME FMEA/CIL WELD JOINTS

Companent Group:

Fuel Turbopumps

CIL Item:

Component: Parl Number: High Pressure Fuel Turbopump RS007501

Prepared: Approved: D. Early T. Nguyen 4/21/99

Approval Date: Change #: Directive #;

2

CCBD ME3-01-5206

Page;

| | | | | | | | | |
|----------------|-------------------|----------------------------|--------------|--------|------------------|--------|----------------------------------|--------------|
| Component | Basic Part Number | Wald Numbe | r Wald Tunn | Class | Root Side Not | Flaw 9 | at Initial Size Not edable | |
| SIIIELO | R0012171 | 1.24, 29-52 | | | Access | HCF | | Comments |
| SHIELD | R0012171 | 26 | GTAW | (i | × | | | |
| LIFT-OFF SEAL | R0019230 | 1, 2 | GTAW | li | | | | |
| SHIELD | R0019788 | 25. 26 | GTAW | JI | X | | | |
| SHIELD | R0019788 | 25. 26 27 50 | GTAW | II | | | | |
| SHIELD | R0019788 | | GTAW | 1 | × | | | |
| SHIFLD | R0019788 | 51, 52 | GTAW | 1 | | | | |
| BELLOWS | RS007505 | 53, 55 | GTAW | 4 | | | | |
| BELLOWS | RS007505 | 1-4 | STAW | ! | | X | | |
| NLET | RS007512 | 5, 6 | E8W | | | X | | |
| NLET | R\$007512 | 4 5-6 | GTAW | 1 | | X | | |
| NLET | RS007512 | 5-6 7-10, 12, 13 | GTAW | 1 | | | | |
| NLET | R\$007512 | 11 | GTAW | ' | | | | |
| NLET | RS007512 | 14 15 | EBW | li | | | | |
| NLET | RS007512 | 16 | GTAW GTAW | | | | | |
| FARING SUPPORT | RS00/524 | 14 | EBW | , | | Х | | |
| EARING SUPPORT | RS007524 | 18 | EBW/ | | | | | |
| EARING SUPPORT | RS007524 | 29, 30 | GTAW | | × | | | |
| EARING SUPPORT | RS007524 | 1°8 | GTAW | | × | Х | | |
| EARING SUPPORT | R\$007524 | 115, 121 | | 1 | × | | | |
| EARING SUPPORT | RS007524 | 120 | E6M GTAM | I | | | | |
| FARING SUPPORT | RS007524 | 229-241 | GTAW | | X | | | |
| OUSING | RS007568 | | GTAW | II | X | | | |
| | 11500/308 | 75 223, 228 230 298 | GTAW | 1 | х | х | х | · • • |
| DUSING | RS007568 | 14 | GTAW | I | | | | |
| DUSING | RS007568 | 48 | EBW | 1 | x | x | × | |
| DUSING | RS0075EB | 49 | GTAW | 1 | x | | | |
| CUSING | R\$007585 | 51 | GTAW | ı | X | х | | |
| DUSING | RSC07568 | 52 | GTAW | 0 | x | | | |
| DUSING | PS007568 | 53 | EBW | ï | ^ | | | |
| | | | | • | | | | |

Component Group: CIL Item: Component: Part Number:

Fuel Turbopumps B200

High Prossure Fuel Turbopump RS007501

D. Early T. Nguyen 4/21/99

Prepared: Approved: Approvel Date: Change #: Directive #:

2 GCBD ME3-01-5206

Page:

2 of 3

| <u> </u> | | | | | | | | Paga: 2 of 3 |
|-----------|-------------------|---|-------------|----------|----------------------------|-------------|-----------------------------------|---------------------------------------|
| Component | Basic Part Number | Weld Number | Meld Tuna | Class | Root Side Not Access | Flaw Det | af Initial Size Not ectable | |
| HOUSING | RS007668 | 55 | | | | ПСР | <u> </u> | Camments |
| HOUSING | R\$007568 | 56 | EBW | 11 | X | | | _ |
| HOUSING | RS007568 | 57, 324 325 | WATE | II | X | | | |
| HOUSING | FIS007568 | 56 58 | GTAW | JF 71 | | | | |
| HOUSING | RSD07568 | 59 | GTAW EBW | II . | x | × | Х | |
| HOUSING | RS007568 | 74, 229, 297 | GTAW | i | | | | |
| IOUSING | RS007568 | 76, 77 | GTAW | • | Х | х | Х | |
| HOUSING | RS007568 | 78-89 | GTAW | ' | | X | | |
| HOUSING | RS007568 | 90-101 | GTAW | 11 | X | | | |
| IOUSING | RSQC75BB | 102 | GTAW | 11 | X | | | |
| OUSING | RS007588 | 139 | GTAW | I 1 | X | | | |
| HOUSING | R\$007558 | 140 | GTAW | " | X | | | |
| HOUSING | RS007598 | 153, 154 | GTAW | 11 | x x | | | |
| HOUSING | RS007568 | 174-185 | GTAW | ii | x | | | |
| HOUSING | RS007568 | 191 +92. 195, 196 245, 455 456 | GTAW | ii | x | x | | |
| HOUSING | RS/107568 | 193, 194, 197-202 204-207 | GTAW | 0 . | | × | | |
| HOUSING . | RS007568 | 203, 217, 218, 234, 236 | GTAW | II | х | X | | |
| IOUSING | R5007568 | | GTAW | II | | | | |
| KONJSING | A\$007568 | 214 215 | GTAW | I | × | | | 1 |
| CUSING | RS007568 | 222, 239 | GTAW | Į. | | x | | |
| IOUSING | RS007568 | 224, 225 | GTAW | ı | | X | x | |
| OUSING | RS007568 | 226, 227 | GTAW | I | | x | ., | \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ |
| OUSING | RS007568 | 231, 232 | GTAW . | II | | x | | |
| OUSING | RS007568 | 233 | GTAW | l4 | x | | | |
| OUSING | RS007568 | | GTAW |] | | | | |
| OUSING | R\$007568 | | GTAW | η | | | | |
| OUSING | R\$007568 | | GTAW | H. | x | | | |
| CUSING | RS007568 | | GTAW | il | x | | | |
| OUSING | RS007568 | | GTAW | ï | | x | х | |

B - 184

CIL Item:

Component: Part Number:

Fuel Turbopumps B200 High Pressure Fuel Turbopump RS007501

Prepared: Approved: Approvel Date: Change #: Directive #:

D. Early T. Nguyen 4/21/99 2

GCBD ME3-01-5206

Page:

| Companent | Proje Bod Monto | | *** | | Critical Initial Root Flaw Size Not Side Not Defectable | |
|------------|-------------------|-------------|-----------|-------|---|----------|
| | Basic Part Number | Weld Number | Weld Type | Class | Access HCF LCF | Comments |
| HDU\$ING | RS007568 | 401-424 | GTAW | II | х | |
| HOUSING | RS007568 | 425-448 | GTAW 1 | lì | Х | |
| HOUSING | RS007568 | 450 (OPT) | GTAW | l: | | |
| HOUSING | RS007568 | 450 (OPT) | EBW | JI | x | |
| HOUSING | RS007568 | 454 | GTAW | Ħ | × | |
| HOUSING | RS007568 | 537 (OPT) | GTAW | 11 | | |
| ROTOR SEAL | RS207589 | 1 | EBW | 1 | | |
| SEA. | #IS007592 | 25 | EBW | Ц | х | |